

Report to: Environment Committee

Report Ref: ENV1915
Meeting Date: 9th March 2020
Agenda Item: 6
Prepared By: Town Clerk



Subject: Speed Indicator Device Repair

1.0 BACKGROUND

The council purchased a portable Speed Indicator Device (SID) in 2018 at a cost of £2,125. The SID acts as both a speed deterrent (by advising drivers they are speeding) and recorded speed data which was published online and shared with the Police.

The SID developed a fault which was identified as it was not possible to obtain data from the device. The company have inspected the device and identified a fault with the radar which requires replacing.

The SID was only covered by a one-year warranty. The cost of a replacement radar (with two-year warranty) is £630 (new) or £450 (reconditioned). The council also requires a new spare battery at a cost of £63.50. The committee has sufficient budget to cover the expenditure.

2.0 DECISIONS REQUIRED

The committee should consider the repair of the SID to enable it to be redeployed.